



RWinvest

CROSBY GARDENS

Construction Update

August 2018



Crosby Gardens **Crosby Road North, Liverpool, L22 0NY**

The latest Crosby Gardens Construction Update details the extensive strip out and removal of materials from the site to make way for new structures. Demolition of internals will proceed shortly as preparation works are underway. The stripping out of toilets, carpet tiles, internal doors and ceilings include some to the key activities continuing to progress.

Works Progressed

- Internal strip out continues.
- Removal of electrical fittings and lighting has progressed.
- Removal of toilet cubicles and vanity units has progressed.
- Ceiling strip outs continue to progress.
- Carpet tile and floor finishes removal is ongoing.
- Removal of the internal studwork is ongoing.
- Removal of internal doors has progressed.
- Furniture removal is nearing completion.
- The current utilities connections have been isolated.
- Preparation works are underway for internal demolition and structural alterations.

If you need any further information in the meantime, please call us at the following offices:

Liverpool +44 (0)151 808 1250

London +44 (0)207 100 4141



