



RWinvest

CROSBY GARDENS
Construction Update
February 2019

Crosby Gardens Crosby Road North, Liverpool, L22 0NY

The progress at Crosby Gardens is well underway with demolition works complete and lift shaft alterations also nearing completion. Work has developed to ventilation, external façade, internal partition walls, corridors, drainage and across several other areas of construction. Tiling is due to commence shortly.

Works Progressed

- Completion of demolition work on the roof and link walkway.
- Near completion of the lift shaft alterations.
- Progression of ventilation.
- Progression of roof works.
- Progression of window installation.
- Progression of external façade works including insulation, render, floor banding and brick slips.
- Smoke shafts and risers progression.
- Progression of internal partition walls including plastering.
- Progression of ceilings and soffits throughout.
- Progression of mechanical and electrical works.
- Joinery progression.
- Internal doors progression.
- Drainage progression.
- Progression of sanitaryware including shower trays.
- Progression of corridors.
- Commencement of tiling.

If you need any further information in the meantime, please call us at the following offices:

Liverpool +44 (0)151 808 1250
London +44 (0)207 100 4141





