



RWinvest

CROSBY GARDENS
Construction Update
September 2018

Crosby Gardens **Crosby Road North, Liverpool, L22 0NY**

The latest Crosby Gardens Construction Update shows all progress at the site in the last construction period. Internal strip out, furniture removal, internal demolitions and lift shaft works are amongst the key activities completed and ongoing at the site.

Works Progressed

- Internal strip out is nearing completion and will be finalised following asbestos removal.
- Furniture removal is complete on the upper floors and ongoing on lower floors.
- Internal demolition is complete to the upper floors and ongoing on lower floors.
- Works to the lift shaft have progressed and removal of old lifts has been completed.
- Scaffolding erection has commenced.
- Forming of corridors has commenced.

If you need any further information in the meantime, please call us at the following offices:

Liverpool +44 (0)151 808 1250

London +44 (0)207 100 4141



